



BGS Cheshire - TH0410

Silixa pre-installation testing on 13/07/2023

- 1. 1 x 115m Composite downhole cable (Fibre Optical & Copper wires) was inspected for any physical damage and OTDR measurements on the optical fibres were performed. The copper wires were also tested with Insulation Resistance Meter. The FOC was intact and the results were saved for further reference.**

Silixa Representative:

A handwritten signature in black ink, appearing to read "Rumen Karaulanov", written in a cursive style.

Rumen Karaulanov

Operations Manager E&I